

# PLASTIFORM<sup>®</sup> 1044/1046 Magnet Material

ROHS COMPLIANT\*\*\*\*

PRODUCT DATA SHEET

## Typical Magnetic Properties

Properties	Anisotropic	
	CGS/U.S.	SI
Br	2450 Gauss	245 mTesla
Hc	2335 Oersteds	186 kA/m
Hci	3225 Oersteds	257 kA/m
BHmax	1.4 MGOe	11.1 kJ/m <sup>3</sup>
Urec	1.06	1.06
Temperature Coefficient of Br	-0.11 %/°F	-0.20 %/°C
Temperature Coefficient of Hci	0.08 %/°F	0.15 %/°C
Peak Magnetizing Force Required	10,000 Oersteds	796 kA/m

## Features

- Nitrile rubber bonded strontium ferrite magnet
- Made by calendaring – sheet process
- Roll Goods
- Refer to the Product Availability Guide for a description of each magnetic material
- Close magnetic tolerances
- Flexible permanent magnet

\* All values shown are measured at 23°C (73°F).

\*\* All values are based on a standard test plug. Consult with an application engineer for more information on your specific requirements.

## Typical Physical Properties

Properties	CGS/U.S.	SI
<b>Mechanical</b>		
Tensile Strength <sup>1</sup>	450 psi	310 Ncm <sup>2</sup>
Elongation at Break <sup>1</sup>	35 %	35 %
Hardness	44 Shore D	44 Shore D
Density <sup>3</sup>	0.134 lbs/in <sup>3</sup>	3.71 g/cm <sup>3</sup>
<b>Electrical</b>		
Volume Resistivity <sup>4</sup>	10 <sup>10</sup> Ohm*cm	10 <sup>10</sup> Ohm*cm
Dielectric Strength <sup>5</sup>	250 v/mil	10 kv/mm
<b>Thermal</b>		
Maximum Continuous Operating Temperature <sup>6</sup>	250°F	120°C
Coefficient of Lin. Ther. Expansion <sup>7</sup> (Thickness)	9.8 x 10 <sup>-5</sup> in/in per °F	18 x 10 <sup>-5</sup> cm/cm per °C

Test Methods

<sup>1</sup>ASTM D-636

<sup>2</sup>Arnold Test Method

<sup>3</sup>ASTM D-297

<sup>4</sup>ASTM D-257

<sup>5</sup>ASTM D-149

<sup>6</sup>Arnold Test Method

<sup>7</sup>ASTM D-696

\* All values shown are typical and are not intended for specification purposes.

\*\*\*\*We have instituted manufacturing procedures designed to restrict the use of hazardous substances. To the best of our knowledge, this product is in compliance with EU Directive 2002/95/EC with respect to lead, mercury, cadmium, hexavalent chromium, polybrominated biphenyls (PBB) and polybrominated diphenyl ethers (PBDE). Notwithstanding the foregoing, we make no warranty as to the fitness of this product for any purpose.

## Flexmag Industries

1000 Magnet Drive., Norfolk, NE 68701

Tel: (800) 328-1373 or (+1) 402-371-6100 Fax: (+1) 402-371-8495

www.flexmag.com

**ARNOLD MAGNETIC TECHNOLOGIES**

# Warranty

---

## Limited Warranty and Exclusive Remedy

Flexmag Industries, Inc. warrants that these products conform to industry standards specific herein and will be free from defects in material and workmanship. THIS WARRANTY IS EXPRESSLY GIVEN IN LIEU OF ANY AND ALL OTHER EXPRESS OR IMPLIED WARRANTIES, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND IN LIEU OF ANY OTHER OBLIGATION ON THE PART OF THE FLEXMAG INDUSTRIES, INC. Flexmag Industries, Inc. will, at its option, repair or replace free of charge (excluding all shipping and handling costs) any products which have not been subject to misuse, abuse, or modification and which in its sole determination were not manufactured in compliance with the warranty given above.

THE REMEDY PROVIDED FOR HEREIN SHALL BE THE EXCLUSIVE REMEDY FOR ANY BREACH OF WARRANTY OR ANY CLAIM ARISING IN ANY WAY OUT OF THE MANUFACTURE, SALE, OR USE OF THESE PRODUCTS. In no event shall Flexmag Industries, Inc. and its parent company, Arnold Magnetic Technologies, be liable for consequential, incidental or any other damages of any nature whatsoever except those specifically provided herein for any breach of warranty or any claim arising in any way out of the manufacture, sale, or use of these products. No other person is authorized by Flexmag Industries, Inc. to give any other warranty, written or oral, *pertaining to the products*.

### **Flexmag Industries**

1000 Magnet Drive., Norfolk, NE 68701  
Tel: (800) 328-1373 or (+1) 402-371-6100 Fax: (+1) 402-371-8495  
[www.flexmag.com](http://www.flexmag.com)

**ARNOLD MAGNETIC TECHNOLOGIES**